

WS024A

Strip Light




Required Tools:
#2 Phillips Screwdriver


Contents:

#	QTY	Part Name
1	01	Strip Light
2	02	Magnetic Mount
3	04	Wood Screw
4	01	4' Power Cord


The Magnetic Mounts are squares located on the top of the Strip Light. Remove film over the adhesive backing and apply Strip Light to the surface where it is to be mounted.




Press the Strip Light against the surface to secure the magnetic mount.
Slide Strip Light off the mounts horizontally.



Secure the magnetic mounts with Provided wood screws



Once the mounts are in place, connect additional Strip Light in chain with 2' Linking Cord and then connect to power source using the 4' Power Cord



SpaceCo Business Solutions, Inc. 800.840.8499 www.spaceco.com

DISCLAIMER OF DAMAGES FOR IMPROPER USE. SpaceCo shall not be responsible for damage to its products, or injuries or damages caused by its products, resulting from improper installation, maintenance, unintended use or attempts to operate such products beyond their mechanical capacity, intentionally or otherwise, or by reason of unauthorized repair. May be covered by issued or pending patents, please see www.spaceco.com/patents for details.